ENVIRONMENTAL CHEMISTS

Date of Report: 01/05/10 Date Received: 12/30/09

Project: Acid Test, PO M124248, F&BI 912247

Date Analyzed: 12/30/09

RESULTS FROM THE ANALYSIS OF AQUEOUS SAMPLES FOR SPECIFIC GRAVITY @ 15.56 °C

Sample ID	Specific Gravity
Laboratory ID	불선 마시 마시다 (해보다)
M124248	1.23
912247-01	

ENVIRONMENTAL CHEMISTS

Date of Report: 01/05/10 Date Received: 12/30/09

Project: Acid Test, PO M124248, F&BI 912247

Date Analyzed: 12/30/09

RESULTS FROM THE ANALYSIS OF AQUEOUS SAMPLES FOR PERCENT ACID

 Sample ID Laboratory ID
 Percent Acid

 M124248 912247-01
 7.9

ENVIRONMENTAL CHEMISTS

Date of Report: 01/05/10 Date Received: 12/30/09

Project: Acid Test, PO M124248, F&BI 912247

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF AQUEOUS SAMPLES FOR SPECIFIC GRAVITY

@ 15.56 °C

Laboratory Code: 912247-01 (Duplicate)

	Sample	Duplicate	Relative Percent	Acceptance
_Analyte	Result	Result	Difference	Criteria
Specific Gravity	1.23	1.23	0	0-2

ENVIRONMENTAL CHEMISTS

Date of Report: 01/05/10 Date Received: 12/30/09

Project: Acid Test, PO M124248, F&BI 912247

QUALITY ASSURANCE RESULTS FROM THE ANALYSIS OF AQUEOUS SAMPLES FOR PERCENT ACID

Laboratory Code: 912247-01 (Duplicate)

				Relative	
		Sample	Duplicate	Percent	Acceptance
1	Analyte	Result	Result	Difference	Criteria
	Percent Acid	7.9	8.0		0-20

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 5, 2010



INVOICE # 10ACU0105-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Acid Test, PO M124248, F&BI 912247 - Results of testing requested by Gerry Thompson for material submitted on December 30, 2009.

1 sample analyzed for Specific Gravity @ \$30 per sample	\$	30.00
1 sample analyzed for Percent Acid Content	Ė	
@ \$75 per sample		75.00
Rush Charges (same day) 150% of \$105.00		<u>157.50</u>
Amount Due	\$	262.50

FEDERAL TAX ID (b) (6)

912247	æ		SA	MPLE	CHAI	IN OF C	US7	OI	Y	1	Æ	10		0/	0	2			HIY				
Send Report To Salas	SAMPLERS (signature)									Page # of TURNAROUND TIME													
Company ALASKAN Copper works Address 628 S. Honora 80 City, State, ZIP Seasone UA 28134 Phone # 206- \$571-6033 266-387-8379				PROJECT NAME/NO. PO # ACIZ TEST m124248							15.	Standard (2 Weeks) RUSH Rush charges authorized by: SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions											
				REMAR	REMARKS E-MAIL RESULTS ASAP GENERAL CHARLES																		
	T								-	11 - 12	ANALYSES REQUESTED												
Sample ID	Lab ID	Date	Time	Sample	туре:	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	% & Acir	Spec. Gearty					Notes				
m 124248	01	12/3/0	10:00	HNE	HNOR		HNO3		NO3 /						•		X	X				AS	AP
19 E	av e																	ASAR					
T of A ore				3	19													1202	300 BILL 100				
				1	v.	[4]				1													
	, n												9										
																	14	9					
																			2/ 				
						7.1																	
						•						i.		FI.				D:					
Friedman & Bruya, Inc.		SIGNATU	RE	PRINT NAME							-	COMPANY						DATE	TIME				
3012 16th Avenue West	Relinguished by	7		Genela Thompsu						4	-						30/08	11:00Am					
Seattle, WA 98119- Ph. (206) 285-8282	Received by: Relinquished by:				Mond Bross						-	FART					//	1/3da	11:00 Apr				
Fax (206) 283-5044	Received by:																						
FORMS\COC\COC.DOC																-							

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 5, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 30, 2009 from the Acid Test, PO M124248, F&BI 912247 project. There are 5 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0105R.DOC